CARRIAGE NUMBER 2
Restoration Diary
Drewry Car No 1327

## July 7, 2022 – First Inspection

Photos: Allan Fairhead














































Photos Pages 2-5: Allan Fairhead



# August 3, 2022 – Removal and Inspection of Seating
















# September 12, 2022 – Further disassembly

Photos: Alan Titheridge

## September 28, 2022 – Asbestos Inspection





Photos - Tina Brown






# October 5, 2022 – Asbestos Removal

Owing to Health and Safety issues, no images of actual work and material disposal available.

Further asbestos located (Photos: Breeze)







Photos: Tina Brown


#### October 21, 2022

## **Driving Cab post Asbestos and Controls Removal**






Photos: Alan Titheridge







### October 21, 2022

## Electrics, disassembled and removed





**Photos: Alan Titheridge** 

**Driver's Wheel** 

### October 21, 2022


## Final bodywork disassembly and Roof Lift





Photos: Alan Titheridge











 ${\it Photos: Above - Alan\ Titheridge}\quad {\it Right-Tina\ Brown}$ 



October 21, 2022
Final bodywork
disassembly and Roof Lift
(continued)



### November 2, 2022 – Chassis





Photos: Tina Brown

#### November 2, 2022 -

#### **Roof relocated to Shed for inspection**

Photos: Below and Top Page 15 Tina Brown





## November 2, 2022 -

## **Discarded timber from disassembly**



Photo: Alan Titheridge



# November 29, 2022 – Roof, internal work complete

Photos: Tina Brown

Left: Internal roof renovation complete

Below: In transit back to workshop





Roof returned to and stored in workshop (Alan Titheridge)

### December 14, 2022 -

#### commencement of construction of side frames









Photos: Alan Titheridge